



GOVERNMENT OF MAHARASHTRA  
Office of the Sub-Divisional Engineer  
Public Works Sub-Division,  
Konkan Bhavan, Navi Mumbai- 400 614



E-Mail :- kokan.de@mahapwd.gov.in	Tel. No. 2757 2676
No. SDE/KB/PB/2023/ 738	Dated :- 20/12/2023

To,

School Engineer,  
Don Bosco Senior Secondary School,  
Plot No 8 Sector 42A,  
Nerul, Navi Mumbai

**Sub.:-** Request to issue the Building Safety Certificate for Don Bosco Senior Secondary School, Plot No 8 Sector 42A, Nerul, Navi Mumbai  
**Ref. :-** Your school principal letter, dt. 20/11/2023.

Sir,

With reference to above subject, the Building safety Certificate of Don Bosco Senior Secondary School, Plot No 8 Sector 42A, Nerul, Navi Mumbai is issued herewith as requested by you.

Encl : Certificate

(R. N. Chavan)  
Sub Divisional Engineer,  
Public Works Sub Division,  
Konkan Bhavan, Navi Mumbai.

ATTESTED

PRINCIPAL  
Don Bosco Senior Secondary School  
Nerul, Navi Mumbai - 400 706.

d:\pc data\lopa\8443\letter\delhi public school.docx

MANAGER  
Don Bosco Senior Secondary School,  
Plot No. 8, Sector 42A, Seawoods,  
Nerul, Navi Mumbai-400706

## BUILDING SAFETY CERTIFICATE

This is to certify that the building of Don Bosco Senior Secondary School, Plot No 8 Sector 42A, Nerul, Navi Mumbai is inspected by the Sub Divisional Engineer, Public Works Sub Division, Konkan Bhavan, Navi Mumbai along with section officer Mr. A. A. Patil on dated 05.12.2023.

On the basis of visual inspection, alongwith the inputs given by the School Engineer and Principal of the School, regarding the construction year and various maintenance activities carried out by the school periodically, it is certified that the Building is safe and sound.

shear cracks are developed on wall it is necessary to repair the same . painting should be done to this crackd wall..Some repairs regarding waterproofing is required to terrace to avoid any kind of leakage, Also the Plaster surface is damaged at various location and the same is required to rectify wherever necessary.

This certificate is issued as per the requirement of CBSE and is valid for the period of one year, only.

DATE- 20/12/2023

  
(R. N. Chavan)

Sub Divisional Engineer,  
Public Works Sub Division,  
Konkan Bhavan, Navi Mumbai.

ATTESTED  
  
PRINCIPAL  
Don Bosco Senior Secondary School  
Nerul, Navi Mumbai - 400 706.

  
MANAGER  
Don Bosco Senior Secondary School,  
Plot No. 8, Sector 42A, Seawoods,  
Nerul, Navi Mumbai - 400706

## BUILDING SAFETY CERTIFICATE

No. 106/2024

Date: 19/03/2024

Certified that the existing building DON BOSCO SENIOR SECONDARY SCHOOL at PLOT NO. 08, SECTOR 42 A , SEAWOODS NERUL, NAVI MUMBAI 400706 comprised of 00 (basement) and G+4 (upper floors) owned/occupied by BOMBAY SALESIAN SOCIETY'S DON BOSCO SENIOR SECONDARY SCHOOL at PLOT NO. 08, SECTOR 42 A , SEAWOODS NERUL, NAVI MUMBAI 400706 have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officer concerned of PUBLIC WORKS DEPARTMENT on Date: 26/02/2024 in the presence of MRS. SANGITA BHATTACHARYA (PRINCIPAL), MRS. JENNIFER DIAS (CLERK) at DON BOSCO SENIOR SECONDARY SCHOOL at PLOT NO. 08, SECTOR 42 A, SEAWOODS NERUL, NAVI MUMBAI 400706 and that the building/premises is fit for occupancy up to CLASS XII with effect from DATE OF ISSUE for a period of 1 YEAR in accordance with rule and subject to compliance of the specific conditions as appended.

1. Toilet, W.C. etc. shall be kept clean for its purpose of use.
2. Adequate fire fighting arrangement should be kept for its full period of use and should be renewed twice in a year.
3. Firefighting equipment shall be suitably located and clearly marked.
4. There should be sufficient light and ventilation in the building.
5. Essential requirements for electrical installation in building to ensure sufficient use of electricity including safety from fire and shock.
6. If any fault or alteration occurred in Building the certificate will be cancelled automatically.

Issued on Date: 19/03/2024 at PWD Thane by

Signature with Seal : \_\_\_\_\_

Name : J. R. Sohdy  
Deputy Engineer


Designation : P.W. Sub. Division No.3,


Name & Address of Department/Office : Thane

(Assistant Engineer & Above officer of Concerned Govt. Department only)

Note: This certificate should be signed / Issued by Assistant Engineer & above officer of concerned Govt. Department only.

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

**ATTESTED**  
  
PRINCIPAL  
Don Bosco Senior Secondary School  
Nerul, Navi Mumbai - 400 706.

  
**MANAGER**  
Don Bosco Senior Secondary School,  
Plot No.8, Sector 42A, Seawoods,  
Nerul, Navi Mumbai-400706